





PWT90




17.5.2017

- D** Montageanleitung
- FR** Notice de montage
- NL** Handleiding voor de montage
- CZ** Montážní návod
- HU** Szerelési útmutató
- TR** Montaj talimatı
- GB** Assembly Instructions
- IT** Istruzioni di montaggio
- PL** Instrukcja montażu
- SK** Návod na montáž
- RO** Instrucțiunile de montaj
- RU** Инструкции по монтажу





20 min.



1



B X26 	C X26 	Z X26 	HD X8 	NGD X4 	ZC X8 	NA X11 	TB X1 	TA X1 	M M4x22 X2 	W3 X2
A X26 	H X10 	HD X8 	NGD X4 	N X14 	NA X11 	TB X1 	ZE X4 	Z X8 	M M4x22 X2 	W3 X2
A X26 	H X10 	HD X8 	NGD X4 	N X14 	NA X11 	TB X1 	ZE X4 	Z X8 	M M4x22 X2 	W3 X2
PC X5 	NC X4 	ZA X1 	ZD X4 	PC X5 	NC X4 	ZA X1 	ZD X4 	PC X5 	NC X4 	ZA X1
PC X5 	NC X4 	ZA X1 	ZD X4 	PC X5 	NC X4 	ZA X1 	ZD X4 	PC X5 	NC X4 	ZA X1





2




- | | |
|----------|----------|
| B | A |
| | |
| X18 | X6 |

3




- | | |
|----------|----------|
| B | A |
| | |
| X4 | X12 |

4



- | | |
|----------|----------|
| H | R |
| | |
| X10 | X5 |
| A | B |
| | |
| X8 | X4 |




4








- | | |
|-----------|-----------|
| NA | ZD |
| | |
| X10 | X4 |
| PC | NC |
| | |
| X5 | X4 |

- | | |
|----------|-----------|
| M | W3 |
| | |
| X2 | X2 |



5






8





9






10




11




12



11



12



- NA
4x13
- TB
x1
- TA
x1
- ZA
x1